# TS100 Quick Start Guide
V1.0

›unitech

TS100
Presentation
Scanner (2D)

## ◄ Horizontal Installation

Install the angle stand upward   Place scanner horizontally

◄ Pitch Forward Installation

Install the angle stand upward   Pitch forward 15°

◄ Connecting The Scanner

Connect USB cable to a free USB port of a host computer. The TS100 is now ready to use.

USB series A shielded connector

◄ Test & Finish

Open a word processing program such as Microsoft Word or Notepad and scan the following barcode:

If the word "Unitech" appears on the screen, you have succesfully installed your scanner.

◄ LED Description

- A green light then a blue light: Switch on
- Blue light always on: Scanner Ready
- Green light flash once: Configuration commands good read
- Red light flash once: Configuration commands error
- Green light flash once: Barcode good read

◄ Buzzer Description

- One long beep: Switch on
- One long and low beep: Configuration commands Error
- One short and low beep: Configuration commands good read
- One short and high beep: Barcode Good Read

◄ Default Setting

Factory Default

Middle

Note: The code with (*) is the factory default.

◄ Beeper Control

Low

High*

◄ Operation Mode

Printed-Reading Mode*

Screen-Reading Mode

We suggest using Screen-Reading Mode when scanning barcodes on the screen. (Default is Printed-Reading Mode)

◄ Good Read Indicator

On*   Off

◄ Display Version

Software Version

◄ Data Terminator

CR*   LF   TAB   CR/LF

◄ Language Settings

USA*   UK   France   Turkey-F

Germany   Italy   Spain   Japan

Brazil   Portugal   Belgium   http://www.ute.com/