

#### OSD and Power Locked:

1. Press the "Menu Key" for 5s to enable / disable the OSD Locking feature.
2. Press the "Menu Key" and the button "Power" for 3s simultaneously to enable / disable the Power Locking feature.

#### Elo Technical Support

Online self-help: [www.elotouch.com/support](http://www.elotouch.com/support)

#### America

800-ELO-TOUCH  
Tel +1 408 597 8000  
[EloSales.NA@elotouch.com](mailto:EloSales.NA@elotouch.com)

#### Asia-Pacific

Tel +86 (21) 3329 1385  
[EloAsia@elotouch.com](mailto:EloAsia@elotouch.com)

#### Europe (EMEA)

Tel +32 (0)16 930 136  
[EMEA.Sales@elotouch.com](mailto:EMEA.Sales@elotouch.com)

The information in this document is subject to change without notice. Elo Touch Solutions, Inc. and its Affiliates (collectively "Elo") makes no representations or warranties with respect to the contents herein, and specifically disclaims any implied warranties of merchantability or fitness for a particular purpose. Elo reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of Elo to notify any person of such revisions or changes.

No part of this publication may be reproduced, transmitted, transcribed, stored in a retrieval system, or translated into any language or computer language, in any form or by any means, including, but not limited to, electronic, magnetic, optical, chemical, manual, or otherwise without prior written permission of Elo Touch Solutions, Inc.

Elo and the Elo logo are either trademarks or registered trademarks of Elo Touch Solutions, Inc.




## Quick Installation Guide

### 04LS Touchmonitors

Revision A  
P/N E878596



1




Remove the screw and cable cover from the touchmonitor.

2




Connect the USB-C cable.  
(Single USB-C cable for power/video/touch function)

3



Install the cable cover first and lock the door with the M3 screw.

4



Monitor can be mounted to any standard 75mmx75mm VESA mounting bracket using four M4 screws.

### Mounting to Elo Z-hinge

---

1



Remove the four M4 screws and 75x75mm VESA adapter from the touchmonitor.

2



Monitor can be mounted to Z-hinge stand using two M4 screws.

Note: refer to the Z10 Stand QIG for details about how to install the Z-hinge stand.

Please go to [www.elotouch.com/support](http://www.elotouch.com/support) to download user manual.

请访问[www.elotouch.com.cn](http://www.elotouch.com.cn)获取用户手册，请保留备用